



**BALLAST MUST BE GROUNDED**  
 Install lamp within 1' of grounded metal plane  
 Insulate unused leads individually for 1000V