

Dimmer Compatibility Test Report

31382R/31382S/36769B

No	Dimmer Brand	Dimmer Model	Dimming Effect					
			1	2	3	4	5	6
1	LUTRON	CT-600P-WH	●	●	●	●	●	●
2	LEVITON	6633-P	●	●	●	●	●	●
3	LEVITON	6683	●	●	●	●	●	●
4	LEVITON	6684	●	●	●	●	●	●
5	LEVITON	IPI06	●	●	●	●	●	●
6	LUTRON	AY-600P	●	●	●	●	●	●
7	LUTRON	CN-600	●	●	●	●	●	●
8	LUTRON	D-603PH	●	●	●	●	●	●
9	LUTRON	LGCL-153PL	●	●	●	●	●	●
10	LUTRON	DV-603PG	●	●	●	●	●	●
11	LUTRON	TTCL-100H	●	●	●	●	●	●
12	LUTRON	TT-300	●	●	●	●	●	●
13	LUTRON	DV-600P	●	●	●	●	●	●
14	LUTRON	GI-600H	●	●	●	●	●	●
15	LUTRON	MACL-153M	/	/	/	/	/	/
16	LUTRON	AYCL-153P	●	●	●	●	●	●
17	LUTRON	TG-600PHLH	●	●	●	●	●	●
18	LUTRON	TGCL-153P	●	●	●	●	●	●
19	LUTRON	DVCL-153PL	●	●	●	●	●	●
20	LEGRAND	CDLV703-PW	●	●	●	●	●	●
21	LUTRON	MA-600	●	●	●	●	●	●
22	LEGRAND	D703-PTC	●	●	●	●	●	●
23	LEGRAND	DLV703-PLA	●	●	●	●	●	●
24	LEVITON	6674	●	●	●	●	●	●
25	LUTRON	DVLV-600	●	●	●	●	●	●
26	LEGRAND	HCL453PTCCCV	●	●	●	●	●	●
27	LEVITON	6672	●	●	●	●	●	●
28	LEVITON	6674	/	/	/	/	/	/
29	LEVITON	6613-P	●	●	●	●	●	●
30	LUTRON	LGCL-153PL	●	●	●	●	●	●
31	LUTRON	DVCL-153P	●	●	●	●	●	●
32	LUTRON	GTJ-250M	●	●	●	●	●	●
33	LEVITON	6631	●	●	●	●	●	●
34	COOPER	DLC03P	●	●	●	●	●	●
35	COOPER	9530WS	●	●	●	●	●	●
36	LEGRAND	H703PTCCCV6	●	●	●	●	●	●

Dimming Effect Remark:

● Good dimming; ◎there is a sudden change in the dimming process; ○flickering at a certain point; □ flickering;

The absence of a dimmer from the list doesn't imply incompatibility.