

76	ACT	3P32ISUNVE	Instant Sart	Y
77	ACT	4P32ISUNVE	Programmed Start	Y
78	ULTRASAVE	UT232347	Instant Sart	Y
79	ROBERTSON	ISL432T8HEMV 3P20160	Instant Sart	Y

Note:

1. Absence of a ballast from this chart does not imply incompatibility. Please reference the ballast manufacturer's instructions for installation and further information.
2. This list is to be used as a general guideline, the LED tube may not work if the ballast is over 5 years old or have a weak starting voltage.
3. Please be cautious and test lamps in fixtures for an extended period of time to ensure proper operation.
4. Do not proceed with a mass installation until proper operation of the LED tube is verified.